

Kuruma
Automotive Refinish 2K

Mixing Color



OEM Match
and easy to spray



Various shades



High solid
and hiding ability



Non-Yellowing
and weathering resistance



HOW TO USE
• ข้อมูลสินค้า • วิธีการ • วิธีการใช้งาน





Kuruma Mixing Color (Solid / Metallic / Pearl)

Description

- High solid and hiding ability
- OEM Match, easy to spray
- Non-Yellowing and weathering resistance
- Various shades

Surface Preparation

- Primer sanding with Dry sanding disc grit No.400 - 500 or Wet sanding grit No.600 - 800
- Clean the surfacer with Kuruma Silicone off to remove dirt, dust and other contaminants

คุณสมบัติ

- เนื้อสีมาก พ่นกลบตัวได้ดี
- เจดสีเหมือน พ่นง่าย
- ทนต่อสภาพอากาศได้ดี ไม่เหลืองตัว
- มีหลากหลายเบอร์ให้เลือกใช้งาน

การเตรียมพื้น

- ขัดสีรองพื้น ด้วยกระดาษทรายกลบขัดแห้ง เบอร์ 400 - 500 เบอร์ 400 - 500 หรือขัดด้วยกระดาษทรายขัดน้ำเบอร์ 600 - 800
- ทำความสะอาดพื้นผิวด้วยคูรูมา น้ำยาทำความสะอาดพื้นผิว ให้ปราศจากคราบไขมัน ฝุ่นละออง และสิ่งแปลกปลอมอื่นๆ

	Mono coat	2 Coat
Mixing Ratio	Weight Solid toner = 100 % Hardener KH041 = 25 % Thinner = 40 - 50 %	Weight Solid toner = 100 % Thinner = 40 - 50 % Weight Metallic toner = 100 % Pearl toner = 100 % Thinner = 70 - 100 %
Spray Viscosity at 30°C	14.0 - 16.0 sec / Ford Cup No.4	
Spray Gun Setting	Gravity Feed Spraying nozzle : 1.3 - 1.4 mm. Spraying air pressure : 1.5 - 2.0 bar	
No. of Coats	2 Full coats	
Dry Film Thickness spray 2-3 coat	Solid toner : 50 - 60 Microns	Solid toner : 30 - 40 Microns Metallic toner : 15 - 25 Microns Pearl toner : 15 - 25 Microns
Flash Time	3 - 5 minutes flash time between coats	
Drying Time at 30°C	Surface dry : 15 - 20 mins. Dry to sand : 4 - 6 hrs.	Surface dry : 3 - 5 mins. Dry to top clear : 5 - 10 mins.
Package Size	Part A : 1 L (12 can / carton) Part B : 0.25 L (12 can / carton)	1 L (12 can / carton) 3.785 L (4 can / carton)

Safety and Disposal

1. For full Health and Safety information, please refer to Material Safety Data Sheet
2. Observe the precautionary notices displayed on the container
3. Goggles and suitable protective equipment must be worn while using these products
4. Good ventilation must be provided in the working environment

ความปลอดภัยในการใช้และการจัดการอุปกรณ์

1. เพื่อความปลอดภัยในสุขภาพ โปรดศึกษาและปฏิบัติตามเอกสารความปลอดภัยอย่างเคร่งครัด
2. โปรดสังเกตและอ่านคำเตือนบนบรรจุภัณฑ์ทุกครั้งก่อนการใช้งาน
3. ระหว่างปฏิบัติงาน ควรสวมใส่อุปกรณ์ป้องกันที่เหมาะสมทุกครั้งที่เกี่ยวข้องกับผลิตภัณฑ์ที่มีส่วนผสมของสารเคมี
4. บริเวณที่มีการปฏิบัติงาน ควรมีอากาศถ่ายเทสะดวก ไม่มีการฟุ้งกระจายของไอพ่นหรือสเปรย์